



BHE GT&S, LLC
10700 Energy Way
Glen Allen, VA 23060

July 24, 2026

BY ELECTRONIC MAIL

Nicholas Bratton
Air Quality Compliance Program
Air and Radiation Management Administration
Maryland Department of the Environment
1800 Washington Boulevard
Baltimore, MD 21230
nicholas.bratton1@maryland.gov
mdeair.othercompliance@maryland.gov

RE: Eastern Gas Transmission and Storage, Inc.
Myersville Compressor Station
Operating Permit No. 021-0707
COMAR 26.11.41.07A
Leak Monitoring Survey Report – Q3 2026

Dear Mr. Bratton:

Pursuant to COMAR 26.11.41.07A(1)(a), BHE GT&S is submitting the required leak monitoring survey report for Myersville Compressor Station's Third Quarter 2026 leak monitoring survey conducted in accordance with COMAR 26.11.41.03.

If you have any questions, please contact Joseph Pietro via email at Joseph.Pietro@bhegts.com.

Sincerely,

A handwritten signature in blue ink, appearing to read "Jeffrey R. Zehner".

Jeffrey R. Zehner, P.E.
Environmental Manager

Attachment

jjp

MARYLAND CERTIFICATE OF DATA ACCURACY


COMAR 26.11.41.07A; Leak Monitoring Survey Report – Q3 2026 Myersville Compressor Station

Company Name: Eastern Gas Transmission and Storage, Inc.
Facility Name: Myersville Compressor Station
Facility Address: 2870 Milt Summers Road
Myersville, Maryland 21769

Permit Number: 021-0707-5-0460 and -5-0461

Federal Tax ID – Plant Code: 55-0629203

I, John M. Lamb, pursuant to **COMAR 26.11.02**, certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Signature: 

John M. Lamb
Vice President, Eastern Pipeline Operations

Date: 7/22/2026



LDAR Report

Eastern Gas Transmission
and Storage, Inc.

Myersville Station - LDAR

Q3 2026 Report
COMAR 26.11.41.07A(1)(a)

SUMMARY

Company:	BHE GT&S		Report:	Q3 2026 LDAR		
District:	EGTS-Eastern		Regulation(s):	COMAR 26.11.41.07A(1)(a)		
Facility Name:	Myersville Compressor Station		Report Date:	July 20, 2026		
GPS Coord.	39.495560	-77.570099	Period:	Jul. 01, 2026	TO	Sep. 30, 2026
This report satisfies the requirements of COMAR 26.11.41.07A(1)(a).						
Information						
Monitoring Quarter	Q1	Q2	Q3	N/A	N/A	
Date of the survey (COMAR 26.11.41.07A(1)(a)(i))	1/14/2026	4/21/2026	7/15/2026	N/A	N/A	
LDAR Instrument	Optical Gas Imaging	Optical Gas Imaging	Optical Gas Imaging	N/A	N/A	
Deviations from Monitoring Plan (COMAR 26.11.41.07A(1)(a)(iii))	No deviations from the Monitoring Plan	No deviations from the Monitoring Plan	No deviations from the Monitoring Plan	N/A	N/A	
Deviation(s) Explanation	N/A	N/A	N/A	N/A	N/A	
Number and type of components for which fugitive emissions were detected (COMAR 26.11.41.07A(1)(a)(iv))						
Valves						
Connectors	1	1				
Pressure Relief Devices						
Open-Ended Lines						
Flanges						
Compressors						
Instruments						
Meters						
Other						
Total No. of Leaks Detected	1	1	0			
Number and type of fugitive emissions components that were not repaired (COMAR 26.11.41.07A(1)(a)(vii))						
Valves						
Connectors	0	0				
Pressure Relief Devices						
Open-Ended Lines						
Flanges						
Compressors						
Instruments						
Meters						
Other			0			
Instrument reading of each fugitive emissions component that requires repair when EPA Method 21 is used for monitoring (COMAR 26.11.41.07A(1)(a)(vi))						
Valves	N/A	N/A	N/A	N/A	N/A	
Connectors	N/A	N/A	N/A	N/A	N/A	
Pressure Relief Devices	N/A	N/A	N/A	N/A	N/A	
Open-Ended Lines	N/A	N/A	N/A	N/A	N/A	
Flanges	N/A	N/A	N/A	N/A	N/A	
Compressors	N/A	N/A	N/A	N/A	N/A	
Instruments	N/A	N/A	N/A	N/A	N/A	
Meters	N/A	N/A	N/A	N/A	N/A	
Other	N/A	N/A	N/A	N/A	N/A	
Number and type of difficult-to-monitor fugitive emission components monitored (COMAR 26.11.41.07A(1)(a)(v))						
Valves	N/A	N/A	N/A	N/A	N/A	
Connectors	N/A	N/A	N/A	N/A	N/A	
Pressure Relief Devices	N/A	N/A	N/A	N/A	N/A	
Open-Ended Lines	N/A	N/A	N/A	N/A	N/A	
Flanges	N/A	N/A	N/A	N/A	N/A	
Compressors	N/A	N/A	N/A	N/A	N/A	
Instruments	N/A	N/A	N/A	N/A	N/A	
Meters	N/A	N/A	N/A	N/A	N/A	
Other	N/A	N/A	N/A	N/A	N/A	

DOR LIST

Fugitive Emissions Components Placed on DOR					
Number and type of fugitive emission components placed on delay of repair and explanation for each delay of repair. (COMAR 26.11.41.07A(1)(a)(viii))					
Component					
Quarter	Q1	Q2	Q3	N/A	N/A
Survey Date	1/14/2026	4/21/2026	7/15/2026	N/A	
Valves					
Connectors	0	0			
Pressure Relief Devices					
Open-Ended Lines					
Flanges					
Compressors					
Instruments					
Meters					
Other					
Total No. of Leaks on DOR	0				
Date Surveyed	Emission ID #	Component Type	Current Repair Status	Delay of Repair Explanation / Justification	

FUGITIVE EMISSIONS AND REPAIR LIST

Fugitive Emissions and Repairs			
List of each fugitive emission and repair. (COMAR 26.11.41.07A(1)(a)(ii) The date of successful repair of the fugitive emissions component. (COMAR 26.11.41.07A(1)(a)(ix) Instrumentation used to resurvey a repaired fugitive emissions component that could not be repaired during the initial fugitive emissions finding. (COMAR 26.11.41.07A(1)(a)(x)			
Date Surveyed	Emission ID #	Date of Successful Repair	Repair Confirmation Method / Instrument
10/8/2025	2599100019	4/22/2026	Bubble Test
1/14/2026	2599100169	2/4/2026	Bubble Test
4/21/2026	3013100306	5/5/2026	Bubble Test